

## Serial Flash Firmware Kit

PowerFlex 400 AC Drives for Fan & Pump Applications  
Catalog Number AK-U9-FLSH1

Installation Instructions

### What's in These Instructions

These installation instructions describe how to update drive firmware using a direct serial flashing process.


**Important:** This kit is not for use with drives which can be flash updated using DriveExplorer™ or DriveExecutive™ software.

The drive's current firmware version can be verified by accessing parameter d320 [Control SW Ver].


### What the Kit Contains

The Serial Flash Firmware update kit includes:


- Flash module
- 1 meter DSI cable with an RJ45 connector and 10-pin double row connector
- 2 meter Serial cable with a locking low profile connector and a 9-pin sub-miniature D-shell female connector
- These Installation Instructions



Flash Module



DSI Cable



Serial Cable

### What You Will Need


- This Serial Flash Firmware Kit
- A field flashable DSI drive
- A PC computer with a free serial communications port and Internet connection
- The DSI\_DriveFlash.exe program and the appropriate Flash file for the drive, available online at: [www.ab.com/support/abdrives](http://www.ab.com/support/abdrives)

### Connect Hardware

1. Remove all power to the drive including any externally supplied control power.




**ATTENTION:** To avoid an electric shock hazard, verify that the voltage on the bus capacitors has discharged before performing any work on the drive. Measure the DC bus voltage at the +DC & -DC terminals of the Power Terminal Block. The voltage must be zero.




2. Disconnect all options connected to DSI ports on the drive.


**Important:** Connected communication options can interfere with the flash process.



3. Connect the DSI cable and the Serial cable to the Flash Module.




4. Connect the 9-pin sub-miniature D-shell female connector of the Serial cable to a serial communications port on a PC computer.




5. Verify that the drive is Enabled.  
The drive is Enabled if:

- ENBL Enable Jumper is installed
- OR
- A valid input is supplied to I/O Terminal 01

Enable Jumper Installed on Control Board




Input at I/O Terminal 01 (2 Wire Control Example Shown)




**Important:** The drive must be enabled during the flash process.

6. With all power removed from the drive, attach the 10-pin connector on the DSI cable to port J2 on the drive control board.




You are now ready to flash update the drive firmware.



## Flash The Drive

- Obtain the latest DSI Drive Flash Tool (DSI\_DriveFlash.exe) and Flash Update File (\*.mot) by connecting to: [www.ab.com/support/abdrives](http://www.ab.com/support/abdrives).
  - Under **Support Options**, click on **Web Updates**.
  - Follow the links for your drive product to download the flash tool and desired flash update file.
- Power up the drive and verify that the Green LED on the Flash Module lights.
- Double click DSI\_DriveFlash.exe file to run the DSI Drive Flash Tool.
  - Review and accept the licence agreement.
- From the DSI Drive Flash Tool's main window:
  - Click Browse and select the desired flash update file.
  - Select the correct serial communications port.
  - Select the desired baud rate. The default baud rate is 57600. If problems occur during the flash routine, this rate can be reduced.
- To begin the Flash Update routine, click the Flash Update button.
- When programming is complete, Exit the DSI Drive Flash Tool.



## Return Drive to Service

1. Remove power to the drive and wait for the Green LED on the Flash Module to go out.

**Important:** If power is reapplied to the drive too quickly, the drive can remain locked in the flash state. If this occurs, remove power to the drive and wait 3 minutes before reapplying power.

2. Disconnect the DSI cable from port J2 on the drive control board.

3. Reconnect communication option if applicable.

4. Restore power to the drive.

- If the drive displays a F100 “Parameter Checksum” fault, cycle power to the drive. Repeat if the fault occurs a second time.

5. Reset parameters to factory defaults. Access parameter P041 [Reset To Defaults] and set to “1”.

6. Access parameter d320 [Control SW Ver] and verify that the updated firmware version is installed.

7. Reprogram the drive for your application.

[www.rockwellautomation.com](http://www.rockwellautomation.com)

---

### Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication RA-IN013A-EN-P – January 2005

P/N 358740-P01

Copyright © 2005 Rockwell Automation, Inc. All rights reserved. Printed in USA.