

ControlLogix DeviceNet Interface Module

Catalog Number 1756-DNB, Series C and D

Topic	Page
About This Publication	1
Before You Begin	1
Enhancement	2
Corrected Anomalies	2
Known Anomalies	4
Additional Resources	4

About This Publication

These release notes correspond to the 1756-DNB module, series C and D, firmware revision 11.003 and earlier.

Before You Begin

Read this section for important information about this product.

IMPORTANT

Revision 11.002 or later is required for the 1756-DNB series D module. Revision 10.x will not run on a 1756-DNB series D module.

To use the USB port, you must have RSLinx software, version 2.51 or later.

If your Logix control program requires Electronic Keying of Exact Match, you must upgrade RSLogix 5000 software to version 17 or later.

2 ControlLogix DeviceNet Interface Module

Enhancement

An enhancement is listed in the table.

Enhancements in Firmware Revision 11.002

Enhancement	Description
Support for the 1756-DNB series D module	This release adds support for the series D module. Firmware 11.x can also be used with the series C module.

Corrected Anomalies

Corrected anomalies are listed in the tables.


Corrected Anomalies in Firmware Revision 11.003

Corrected Anomaly	Description
Messages referencing attribute ID 0 were not sent properly on the DeviceNet network.	If an explicit message was sent through the 1756-DNB module and that message referenced attribute ID 0, the attribute ID was stripped from the message before the message was sent on the DeviceNet network. Lgx00090090

Corrected Anomalies in Firmware Revision 11.002

Corrected Anomaly	Description
Potential lockout of a slave device on a network	If a series C firmware revision 10.x module is on a network with another master, the series C firmware revision 10.x module could lock out a slave device that is in the scanlist of the other master. Lgx00084208, Lgx00084998

Corrected Anomalies in Firmware Revision 10.005

Corrected Anomaly	Description
Data value of -273817920 (0xEFADDEC0) appeared in controller input tag	When the connection from the Logix controller to the 1756-DNB series C module was reestablished, the data in the input tag for the 1756-DNB module was invalid until the first input packet was received from any node on the DeviceNet network in the 1756-DNB scan list. If the connection was reestablished after the 1756-DNB module was power cycled, a data value of -273817920 (0xEFADDEC0) appeared in the input tag until the first input packet was received. <p style="text-align: right;">Lgx00082315</p>
Module faulted when using Advanced Mapping	The 1756-DNB module faulted when using Advanced Mapping for the Input Table or Output Table, with bit offsets or data sizes that are not multiples of 8 bits. <div style="text-align: center;">  </div> <p style="text-align: right;">Lgx00082314</p>
1756-DNB module sent a change-of-state (COS) packet without waiting for an ACK	The 1756-DNB module sent a COS packet after sending a heartbeat packet without waiting for an ACK from the target node. <p style="text-align: right;">Lgx00081482</p>

Known Anomalies

Known anomalies are listed in the table.

Known Anomalies in Firmware Revision 11.002 and Previous Revisions

Anomaly	Workaround
Flash update of 1756-DNB module fails when using ControlFlash software via DeviceNet port	Flash update the 1756-DNB module via the ControlLogix backplane or via the USB port. Lgx00081806
Flash update of multiple modules simultaneously via USB port can fail	Do not flash update more than one module simultaneously over the USB port. Lgx00067859

Additional Resources

These documents contain additional information concerning related Rockwell Automation products.

Resource	Description
ControlLogix DeviceNet Scanner Module Installation Instructions, publication 1756-IN566	Provides information about how to install your module.
DeviceNet Modules in Logix5000 Control Systems User Manual, publication NET-UM004	Provides information about how to use your module after installation.

You can view or download publications at <http://literature.rockwellautomation.com>. To order paper copies of technical documentation, contact your local Rockwell Automation distributor or sales representative.

Allen-Bradley, ControlFLASH, ControlLogix, Logix5000, Rockwell Automation, RSLinx, RSLogix 5000, and TechConnect are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444
Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640
Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1756-RN660B-EN-P - December 2008

PN-36382

Supersedes Publication 1756-RN660A-EN-P - July 2008

Copyright © 2008 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.