

ControlLogix Redundancy System, Revision 15.61

Catalog Number 1756-CNB/D, 1756-CNB/E, 1756-CNBR/D, 1756-CNBR/E, 1756-ENBT, 1756-EWEB, 1756-L55, 1756-L55M12, 1756-L55M13, 1756-L55M14, 1756-L55M16, 1756-L55M22, 1756-L55M23, 1756-L55M24, 1756-L61, 1756-L62, 1756-L63, 1757-SRM

Topic	Page
About This Redundancy Firmware	2
Compatible Software Versions	2
Corrected Anomaly in Revision 15.61	4
Enhancements in Revision 15.60	6
Corrected Anomalies in Revision 15.60	7
Enhancements in Revision 15.57	9
Corrected Anomalies in Revision 15.57	9
Corrected Anomalies in Revision 15.56	9
Corrected Anomalies for Firmware Revision 11.003	11
Corrected Anomalies for Firmware Revision 11.002	12
Enhancements for Firmware Revision 11.002	12
Application Notes	12
Restrictions	13
Known Anomalies	15
Update a System That Is Already at Revision 11 or 13	16
Store a Project to Nonvolatile Memory While Your Process is Running	24
Change CNB modules from Series D to Series E	25
Additional Resources	31

About This Publication

These release notes describes enhancements, corrected anomalies, and known anomalies specific to redundancy system firmware, revision 15.

Information newly-added to this release note, that is, information about changes with revision 15.61, is indicated by change bars like the one shown to the right of this paragraph.

About This Redundancy Firmware

This combination of individual firmware revisions make up revision 15.61 of the ControlLogix redundancy system.

Module	Catalog Number	Series	Firmware Revision
ControlLogix5555 controller	1756-L55Mxx	Any	15.61
ControlLogix5561 controller	1756-L61	Any	15.61
ControlLogix5562 controller	1756-L62	Any	15.61
ControlLogix5563 controller	1756-L63	Any	15.61
ControlNet bridge module	1756-CNBR	D	7.13
		E	11.003
1756 10/100 Mbps EtherNet/IP Bridge, Twisted Pair Media	1756-ENBT	Any	4.4
1756 10/100 Mbps EtherNet/IP Bridge w/ Enhanced Web Services	1756-EWEB	Any	4.4
Redundancy module	1757-SRM	Any	4.6

Compatible Software Versions


To use this redundancy firmware revision, you need these software versions.

Software	Version	Notes
RSLinx	2.51	
1757-SRM System Redundancy Module Configuration tool	3.6.4	<p>Important: Do not update your 1757-SRM Configuration tool at this time. See the section titled Update a System That Is Already at Revision 11 or 13 on page 16.</p> <p>Get Knowledgebase document 29511. To access Rockwell Automation's Knowledgebase, go to http://support.rockwellautomation.com</p>
RSLinx Enterprise	3.0	<p>You need this software only for use with these HMIs:</p> <ul style="list-style-type: none"> • PanelView Plus terminal • VersaView industrial computer running a Windows CE operating system • RSView Supervisory Edition software <p>Important: For RSView Supervisory Edition software, install the RSLinx Enterprise HOTFIX. The HOTFIX improves the EtherNet/IP switchover time. See Knowledgebase document R154640079. To access Rockwell Automation's Knowledgebase, go to http://support.rockwellautomation.com</p>
RSLogix 5000	15.02	
RSNetWorx	5.11	


How Do I Tell Which Version of the Configuration Tool I Have?

To see which version of the 1757-SRM System Redundancy Module Configuration tool that you have, complete these steps.


1. Start RSLinx programming software.
2. From the Communications pull-down menu, select RSWho.



3. Browse to and right-click your 1757-SRM module and choose Module Configuration.



The Module Configuration dialog appears.



4. Right-click the title bar and choose About to verify the version of your configuration tool.

Corrected Anomaly in Revision 15.61

This section describes the anomaly specific to the use of redundant systems that has been corrected with revision 15.61.

System Behavior That Indicates the Anomaly

The anomalous behavior described here may rarely occur in certain redundancy applications.

When a redundancy system has been operating in a synchronized state for an extended period of time, a backplane communication error may occur and trigger this sequence of system behaviors:

1. The 1757-SRM displays error code E054.
2. A Watchdog timeout occurs on the controller program and the OK status indicators flash red (1756-L6x controllers), or, are steady red (1756-L55 controllers), indicating the major fault.
3. A redundant chassis switchover occurs in response to the 1757-SRM error.
4. ControlNet communication modules in the new primary chassis fault as indicated by:
 - the loss of the ControlNet modules from the ControlNet network. That is, the modules no longer display when the ControlNet network is browsed via RSLinx software - though they will display if you browse across the backplane.
 - the ControlNet modules' channel status and module status indicators flash red.

As a result, the ControlNet modules are no longer able to communicate with remote I/O.

If you experience the faults described above, upgrade to redundancy revision 15.61.

If you have not experienced the faults described above, you may still need to upgrade to revision 15.61. See System Conditions That Contribute to Anomalous Behavior, on [page 5](#), for descriptions of conditions that may cause the backplane communication fault and trigger the anomalous behavior.

System Conditions That Contribute to Anomalous Behavior

Even if your redundancy system does not exhibit the anomalous behavior described above, you may still need to consider upgrading to redundancy firmware revision 15.61.

Consider upgrading to 15.61 to avoid anomalous behavior if you use three or more modules in the redundant chassis (including the 1757-SRM) and **either** of these application conditions exists:

- Extensive messaging occurs through one or more communication bridges, typically 1756-CNB/D or 1756-CNB/E modules, at a rapid rate (that is a rate in terms of milliseconds).

Extensive messaging for the purposes of this anomaly correction is defined as any one of the following:

- greater than 50 block transfers through a single bridge module to remote I/O.
- two or more messages that are triggered concurrently and are repeated at short time intervals.
- several individual messages that are executed immediately following one another.

For example, extensive messaging is commonly used in 1771 applications where analog I/O is heavily used.

- The controller program has **all** of these elements:
 - unconnected messaging is used.
 - high-priority tasks with scan times greater than 100 msec that have minimal data or output tag changes.

Corrections With Firmware Revision 15.61

With this redundancy system revision, corrections have been made to both controller and redundancy module firmware to resolve the anomalous behavior.

Component Firmware	Description of Correction
Controller	With redundancy firmware revision 15.61, the controller firmware has been revised to eliminate the internal condition that triggers the backplane communication fault. Lgx00093855
System redundancy module	As a precaution, with this redundancy module revision, changes have been made so that if a backplane communication fault were to occur, it is rapidly detected and indicated by error code E2LH displayed on the 1757-SRM. The rapid detection results in a faster switchover to the secondary chassis. The decreased switchover response-time lessens the likelihood of faults in new primary chassis. Lgx00094714

Enhancements in Revision 15.60

These enhancements apply only to controllers in a redundant system. For the list of enhancements for all systems, see the ControlLogix Controller Revision 15 Release Notes, publication [1756-RN620](#).

Enhancement	Description
Update the firmware of a redundant chassis while process is running.	If your system is at revisions 11 or 13, you may update the firmware in your redundant chassis without shutting down your process.
Use up to seven communication modules in your local chassis.	If your system is at revision 15.60, you may use any combination of up to seven communication modules in your local chassis.
Update a 1756-L55 controller to a 1756-L63x controller.	If your system uses 1756-L55 controllers in a redundant system, you can update a 1756-L55 controller to an appropriate 1756-L6x controller without shutting down your process. However, you cannot convert a 1756-L6x controller to a 1756-L55 controller. If the controller you want to update is a secondary controller, it must have at least as much memory as the primary controller in your redundant system.

Corrected Anomalies in Revision 15.60

Revision 15.60 corrects these anomalies in redundant system controllers.

Corrected Anomaly	Description
The redundant system chassis does not consistently allow I/O modules to be deleted while the system is running.	The redundant system chassis does not consistently allow I/O modules to be deleted while the system is running. The controller produces the error message "delete add online.bmp". To delete the I/O module, disqualify the secondary chassis. Lgx00074233
In rare instances, the removal of a data table from the primary chassis can fault the secondary chassis.	In rare instances, the removal of a data table tag from the primary chassis can fault the secondary chassis. This major fault typically occurs on the first attempt to remove the data table tag. Lgx00073781
The 1756-L63 controller, Series B, becomes stuck in Run mode during the transition to Program mode.	The 1756-L63 controller, Series B, becomes stuck in Run mode during the transition to Program mode. Outputs are also disabled. Do not increment the sequence number for Class 3 connection responses when reenabling autotransmit. Doing so causes the controller to respond to the incorrect incoming messages that arrive during a switchover, preventing the transition to Program mode. Lgx00073590
The secondary controller in a redundant system faults if the network trunkline is broken.	The secondary controller in a redundant system faults if the network trunkline is broken. Lgx00073583
Communication modules in the RSLogix 5000 controller organizer display as dropped connections after a switchover. This may cause the controller to experience a major fault if the modules were configured to fault on connection failures.	Communication modules in the RSLogix 5000 controller organizer display as dropped connections after a switchover. These modules have signature mismatches but do not have any connection paths to or through them. When the controller organizer displays these modules as dropped connections, the controller's I/O LED indicator momentarily flashes green, possibly causing a major controller fault. Lgx00072933
Outgoing serial port messages that contain errors eventually cause an unrecoverable controller fault.	Outgoing serial port messages that contain errors eventually cause an unrecoverable controller fault. Lgx00072891
Cycling the power during the qualification of a secondary controller causes an unrecoverable controller fault when power is reapplied.	Cycling the power during the qualification of a secondary controller causes an unrecoverable controller fault when power is reapplied. Lgx00072619
Cable disconnections can cause a switchover to occur. Completion of the switchover may also cause connections to be dropped.	Cable disconnections can cause a switchover to occur. Completion of the switchover may also cause I/O connections to be dropped. Lgx00072255
In rare instances, changing the controller from Run to Program mode causes a switchover.	In rare instances, changing the controller from Run to Program mode causes a switchover. An unrecoverable fault on the original primary controller causes the switchover. Lgx00071488
If you use an HMI to monitor program-scoped tags, the controller will experience an unrecoverable fault during an application download.	If you use an HMI to monitor program-scoped tags, the controller will experience an unrecoverable fault during an application download. RSLogix 5000 programming software causes this fault. Lgx00071478
When the primary controller is processing inbound messages, you may not be able to lock the controller for update if your application uses >12,000 symbols.	When the primary controller is processing inbound messages, you may not be able to lock the controller for update if your application uses >12,000 symbols. Decreasing the number of symbols from 20,000 to 12,000, for example, would reduce from 490 ms to approximately 280 ms the time required for the controller to execute communication commands. Lgx00070173

If power is cycled to the secondary controller while it is being locked for update, after the power is reapplied to the secondary controller, the redundant system will see the secondary controller as the primary controller.	If power is cycled to the secondary controller while it is being locked for update, after the power is reapplied to the secondary controller, the redundant system will see the secondary controller as the primary controller. Consequently, the system will no longer be redundant, having no secondary controller. Lgx00070171
After ControlNet scheduling, the secondary controller can experience an unrecoverable fault.	After ControlNet scheduling, the secondary controller can experience an unrecoverable fault if a tracked command in the primary controller is crossloaded to the secondary controller before the secondary controller can execute the command. Lgx00069672
If the communication modules in the RSLogix 5000 controller organizer are not named, you will not be able to lock the controller for updating.	If the communication modules in the RSLogix 5000 controller organizer are not named, you will not be able to lock the controller for updating. The secondary controller sees these unnamed I/O modules and assumes that they do not match those in the primary chassis. Lgx00069912
The 1757-SRM redundancy module in the secondary chassis fails during a switchover.	The 1757-SRM redundancy module in the secondary chassis fails during a switchover. The failure occurs if the secondary 1757-SRM module is in steady state PwQS. Lgx00071769
A synchronization command to the primary 1757-SRM redundancy module fails.	When a disqualification command is sent to the primary 1757-SRM module, and is immediately followed by a synchronization command to the primary 1757-SRM module, the synchronization command is accepted, but the secondary 1757-SRM module remains disqualified. Lgx00058896
The SRM Configuration Tool does not allow a new folder to be created in the Save As dialog.	The SRM Configuration Tool does not allow a new folder to be created in the Save As dialog. RSLinx has been fixed. Lgx00054034
The SRM Configuration Tool does not allow you to enter a date and time from your keyboard.	The SRM Configuration Tool does not allow you to enter a date and time from your keyboard. The tool's controls override the keyboard entries. Use the drop-down date control menu to select a date and time. Lgx00054034
Pulling a 1757-SRM module out of a primary chassis sometimes faults the secondary controller after the switchover.	If your redundant chassis are synchronized and you pull the 1757-SRM module out of the primary chassis, a switchover happens and the new secondary controller (old primary) could end up with a nonrecoverable fault (solid red OK light). Lgx00067758
When EPM objects are added, no synchronization points exist for these objects.	Because no synchronization points exist for EPM objects that are added, to force a synchronization point, place an empty normal program in the task's program list indicating where the synchronization point is to occur. Lgx00062555

Enhancements in Revision 15.57

These enhancements apply only to controllers in a redundant system. For the list of enhancements for all systems, see ControlLogix Controller Revision 15 Release Notes, publication 1756-RN620.

Enhancement	Description
Update the firmware of a redundant chassis while process is running.	If your system is at revision 13, you may update the firmware in your redundant chassis without shutting down your process.
Add I/O modules while online.	At runtime, you can add 1756 I/O modules to a remote chassis via the unscheduled portion of a ControlNet network.

Corrected Anomalies in Revision 15.57

Revision 15.57 corrects these anomalies in redundant system controllers.


Corrected Anomaly	Description
With 1756-L55Mxx controllers, data was not updated in the secondary chassis while the system was locked for update.	This was only an issue with 1756-L55Mxx controllers. When the system was locked for update, the data in the secondary chassis was not updated. Once the switchover occurred, the new primary chassis used the old data. Lgx00069959
If 1756-L55Mxx controllers automatically loaded a project from nonvolatile memory, there was a nonrecoverable fault.	If 1756-L55Mxx controllers were configured to load a project on powerup or when the nonvolatile memory was empty or corrupt, there was a nonrecoverable fault. Lgx00068091

Corrected Anomalies in Revision 15.56

Revision 15.56 corrects these anomalies in redundant system controllers.

Corrected Anomaly	Description
The File Search Compare (FSC) instruction caused a nonrecoverable fault.	The FSC instruction caused a nonrecoverable fault if: <ul style="list-style-type: none"> · a major fault was declared from within the expression of an FSC instruction. · the user fault routine cleared the fault. Lgx00055522
You could not send an SLC-typed write message to a redundant controller.	An SLC-typed write message to a redundant controller produced error F007. Lgx00058402
Memory changes during prescan were not always crossloaded.	Sometimes the primary controller did not send data changes that it made during prescan to the secondary controller. Lgx00060517
Some data-table-write services were not immediately forwarded to the secondary controller.	Data-table-write, big-write, and read-modify-write services were not immediately forwarded to the secondary controller if the service used a symbolic address. Instead, they were forwarded after the next program scan. Lgx00060643

Corrected Anomaly	Description
A secondary 1757-SRM module faulted with an E888 error if you unplugged a 1756-CNB module.	<p>The secondary 1757-SRM module sometimes faulted while synchronized if you unplugged the tap to a secondary 1756-CNB module. The error code of the 1757-SRM module was E888. This error code disqualified the chassis.</p> <p>You had to remove and reinsert the secondary 1757-SRM module under power to recover. Lgx00060989</p>
A synchronized chassis pair did not automatically synchronize after being disqualified.	<p>The redundant chassis pair did not automatically synchronize after multiple cycles of disqualification caused by either unplugging the tap to a secondary 1756-CNB module or power-cycling the secondary chassis.</p> <p>You had to remove and reinsert the secondary 1757-SRM module under power to recover. Lgx00061808, Lgx00060991</p>
Sometimes a module faulted after a switchover.	<p>Sometimes a module would fault after a broken or disconnected communication cable caused a switchover. The module showed a fault code of 16#0022.</p> <p>Lgx00061990</p>
The 1757-SRM module pair lost the fiber optic connection under heavy HMI traffic.	<p>The synchronized pair of 1757-SRM modules would sometimes lose their connection across the fiber-optic link under heavy HMI traffic conditions. This caused the secondary chassis to become disqualified either with the 1757-SRM modules showing no partner or the secondary module showing error EA91</p> <p>You had to remove and reinsert the secondary 1757-SRM module under power to recover. Lgx00062847, Lgx00062839, Lgx00062171</p>
The primary 1757-SRM module rejected a synchronization command.	<p>The primary 1757-SRM module rejected a synchronization command when both these conditions were true:</p> <ul style="list-style-type: none"> · The auto-qualification option was set to Never. · You gave the synchronization command within 30 seconds of the redundant chassis pair being disqualified. <p>The 1757-SRM module continued to reject any synchronization command. You had to change the auto-qualification option to Always to synchronize the chassis. Lgx00062954, Lgx00058896, Lgx00037660</p>
A 1756-ENBT module would not reply to a ping.	<p>Sometimes you would not get a reply when you pinged a 1756-ENBT module.</p> <p>Lgx00062979</p>

Corrected Anomaly	Description
Updating a primary 1757-SRM module caused a nonrecoverable fault.	Updating the firmware of a 1757-SRM module in a primary chassis sometimes caused a nonrecoverable fault in the controller. This happened if the controller ran out of outgoing unconnected buffers. Lgx00063005
CompactFlash image caused a major fault.	A controller had a major fault if you: <ul style="list-style-type: none"> · stored a CompactFlash image using a controller that was last powered down as a disqualified secondary controller. · configured the image to go to run mode after loading. Lgx00063515
You could not download to a disqualified secondary controller without enough memory reserved for logic.	<p>You could not download to a disqualified secondary controller if the slider was too close to Tags.</p>  Lgx00063587

Corrected Anomalies for Firmware Revision 11.003

These anomalies have been corrected in firmware revision 11.003, series E of the 1756-CNB and 1756-CNBR modules.

Anomaly	Description
The 1756-CNB sends an extra report event during a locked switchover.	The 1756-CNB module sends an extra error report to the 1757-SRM during a locked switchover. This extra report prevents the 1757-SRM from responding to the locked switchover command. Lgx00073886 and Lgx00073887
The 1756-CNB faults when the workstation is booted up.	The 1756-CNB module is faulting when the workstation is booted up because the ISR is posting event flags. A new message queue size of 100 will force a task to wait for an event flag to be posted. Lgx00066493
The 1756-CNB module faults if power is applied simultaneously to both chassis of a redundant pair.	The 1756-CNB module faults if power is applied simultaneously to both chassis of a redundant pair. The fault is DUPL NODE !Cpt. Lgx00071468

Corrected Anomalies for Firmware Revision 11.002

These anomalies have been corrected in firmware revision 11.002, series E of the 1756-CNB and 1756-CNBR modules.

Anomaly	Description
1756-CNB and 1756-CNBR modules stop communicating.	<p>All 1756-CNB and 1756-CNBR modules with firmware revisions prior to 11.002 will stop communicating after 70.96 days of powered operation. If this occurs, the OK LED indicator will be solid red and the 4-character display on the front of the module will either freeze or scroll the message: ASSERT main.c line 1231.</p> <p>This problem can be avoided by removing and reinserting the ControlNet module, or cycling power to the chassis within the 71 days. Because the module will halt in another 70.96 days, you must perform a mandatory firmware upgrade to revision 11.002.</p>
1756-CNBR module may revert to using only channel A.	If the 1756-CNBR module is the only active keeper on the network while cycling power or there is a disruption, the module may revert to using only channel A.

Enhancements for Firmware Revision 11.002

For series E of the 1756-CNB and 1756-CNBR modules, the release of revision 11 added the support to perform firmware and software upgrades to a running ControlLogix Redundancy configuration.

Application Notes

Minimum Value for the Watchdog Time

Set the watchdog time for each task to this value or more:

$$\text{Minimum watchdog time} = (2 * \text{maximum_scan_time}) + 150 \text{ ms}$$

where:

Maximum_scan_time is the maximum scan time for the entire task when the secondary controller is synchronized.

Restrictions

IMPORTANT

In a redundant system, use an EtherNet/IP network only for HMI/workstation communication and messaging.

Do not use an EtherNet/IP network for:


- communication with I/O modules.
- communication between devices via produced/consumed tags.

Restriction	Details
Attempting to update a system with busy 1756-L55Mxx controllers will result in a loss of system control.	<p>A system that is locked for update requires additional processor resources. A CPU utilization of a synchronized pair of 1756-L55Mxx controllers that exceeds 80% suggests that adequate processor resources are not available to your application.</p> <p>For additional information on how to verify if your application can provide adequate processor resources during a system update, consult these publications.</p> <ul style="list-style-type: none"> · ControlLogix Redundancy System User Manual, publication 1756-UM523 · Logix 5000 Controllers Design Considerations Reference Manual, publication 1756-RM094
Do not upgrade a 1757-SRM module from version 2.xx or earlier directly to version 4.3 or later.	Flashing a 1757-SRM module from version 2.xx or earlier directly to version 4.3 or later causes the 1757-SRM module to become permanently inoperable. To avoid this from occurring, you must first flash the 1757-SRM module to any of the versions 3.xx included in the version 13 redundancy bundles. Once the 1757-SRM module is at one of the versions 3.xx, you can successfully flash to version 4.xx.
Do not use ControlLogix5564 controllers.	You cannot use this revision with 1756-L64 controllers.
Do not use 1756-CN2 modules in a redundant chassis.	You cannot use this revision with 1756-CN2 ControlNet bridge modules in a redundant chassis.
Do not use equipment phases.	This revision will not let you download a project that has equipment phases, nor will it let you create equipment phases online.
Version 2.6 or later of the 1757-SRM configuration tool does not work with revision 11 or earlier systems.	<ul style="list-style-type: none"> • Version 2.6 or later of the 1757-SRM System Redundancy Module Configuration tool does not work with revision 11 or earlier redundancy systems. You can cause the 1757-SRM module to fault. • Use version 2.6 or later of the configuration tool only with revision 13 or later ControlLogix redundancy systems. • RSLinx programming software, version 2.43 or later, automatically installs version 2.6 or later of the configuration tool. • To connect to a revision 11 or earlier redundancy system, remove the configuration tool and install a compatible version. Use version 2.5 of the configuration tool for revision 11 redundancy systems.

Restriction	Details		
<p>Make sure your 1756-ENBT modules are catalog revision E01 or later.</p>	<p>To use a 1756-ENBT module in a redundant controller chassis, make sure its catalog revision is E01 or later. Otherwise, the secondary chassis will not synchronize with the primary chassis.</p> <div data-bbox="613 415 1019 520" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <table border="0"> <tr> <td style="padding-right: 10px;"> Allen-Bradley ControlLogix CAT. NO./SERIES 1756-ENBT/A </td> <td> Ethernet/IP 10/100 Mb/s COMMUNICATIONS BRIDGE CAT. REV. E01 </td> </tr> </table> </div> <p style="margin-left: 400px;">To find the catalog revision of a module, look at the label on the side of the module or box.</p> <p style="margin-left: 400px;">Catalog Revision</p> <p>Example: Use a catalog revision of E01, E02, ..., F01, for example.</p>	Allen-Bradley ControlLogix CAT. NO./SERIES 1756-ENBT/A	Ethernet/IP 10/100 Mb/s COMMUNICATIONS BRIDGE CAT. REV. E01
Allen-Bradley ControlLogix CAT. NO./SERIES 1756-ENBT/A	Ethernet/IP 10/100 Mb/s COMMUNICATIONS BRIDGE CAT. REV. E01		
<p>For a series B controller with revision 1.7 firmware, use a nonredundant chassis to update it the first time.</p>	<p>Example</p> <p>Once out of its box, your controller's label shows it to be series B, with revision 1.7 firmware.</p> <div data-bbox="841 804 1222 972" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p>The image shows a label for an Allen-Bradley controller. On the left, it says 'Allen-Bradley' and '1756-L63(B)'. On the right, it says 'LOGIX 5563 PROCESSOR UNIT' and 'CATALOG REV. PART NO.' with a circled '1.7' next to it. A callout bubble with 'B' points to the series letter, and another callout bubble with '1.7' points to the revision number.</p> </div> <p>In this case:</p> <ol style="list-style-type: none"> 1. Put the controller in a nonredundant chassis. 2. Update the controller. 3. Put the controller in the redundant chassis. <p>Otherwise the controller will have a nonrecoverable fault.</p> <p>After you update it the first time, you can update it in the redundant chassis from then on.</p> <p>Exception</p> <p>The controller is already running in your system. You want to update it to a later revision. In this case, leave it where it is and update it there.</p>		

Give a 1757-SRM module several minutes or more to update. It takes several minutes to update a 1757-SRM module and the module resets itself at least four times. A 1757-SRM module with revision 3.37 or earlier firmware may become inoperative if you interrupt the update process.

Wait until you see this box turn green and say Update complete.



If the update fails, leave the power on and try again. The update failed if you see:

- the Update Status window turn red and say the update failed.
- that the OK LED indicator on the 1757-SRM module is flashing and the four-character display is blank.

Restriction	Details
Wait at least 45 seconds after the redundant chassis are disqualified before you try to synchronize them.	If your secondary chassis becomes disqualified or you manually disqualify it, do these actions before you try to synchronize the chassis: <ul style="list-style-type: none"> · Make sure the synchronization status of the primary modules is full compatibility. · Wait at least 45 seconds before you give the command to synchronize the secondary chassis.
If you unplug the fiber optic cable between the 1757-SRM modules, wait until they stabilize before you reconnect it.	If you unplug the fiber-optic cable between the 1757-SRM modules, check the synchronization status of the secondary 1757-SRM module before you reconnect the cable. Wait until the module's status is secondary with no partner before reconnecting the cable. Otherwise, the secondary 1757-SRM module could fault with an EA91 error.

Known Anomalies

Known Anomaly	Description
Perform online edits during a switchover.	In some instances, RSLogix 5000 programming software may not let you perform additional online edits of a function block, SFC, or structured text routine. This may occur if you edit the routine while online and the system is switching over and synchronizing. If this occurs: <ol style="list-style-type: none"> 1. Close and then reopen RSLogix 5000 programming software. 2. Upload the RSLogix 5000 project from the primary controller.
Delete a task or unschedule a program online.	The secondary chassis may disqualify and then synchronize if you: <ul style="list-style-type: none"> · delete a task while online with the controller. · unschedule a program while online with the controller.
ASCII instructions may prevent the secondary controller from synchronizing.	After you download a project that contains ASCII instructions (for example, ABL, ACB) to a pair of redundant controllers, the secondary controller may disqualify and fail to synchronize. If this occurs, turn off both controllers (primary and secondary) and then turn them back on.
Controller may momentarily drop its connection to a digital I/O module.	In rare instances, if a tap to a 1756-CNB module is disconnected or broken, the primary controller may momentarily drop its connection to a digital I/O module in local or remote chassis. The connection automatically reestablishes itself. To minimize the chances of this happening, use redundant ControlNet media. Redundant ControlNet media prevents a loss of communication if a trunkline or tap is severed or disconnected.
Sometimes a secondary 1757-SRM module rejects a command.	Sometimes the secondary 1757-SRM module rejects a synchronization, disqualification, or switchover command. To avoid this, give the command to the primary 1757-SRM module. Lgx00058897
Secondary 1756-ENBT module sometimes stops communicating after a power cycle.	A 1756-ENBT module in a secondary chassis sometimes stops communicating after you cycle power to it. Lgx00062494

Known Anomaly	Description
Fail to synchronize with a high connection count.	The chassis can fail to synchronize if the controller is near its connection limits. Lgx00063311
Commanding a secondary chassis to become primary while turning on its partner causes a fault.	The secondary 1757-SRM module can fault if you command it to become primary while you are turning on the partner chassis. The 1757-SRM module shows an EAAH error. To avoid this, wait until the secondary chassis completes its transition to Primary with No Partner before turning on the partner chassis. Lgx00063356
A secondary 1756-ENBT module sometimes will not synchronize if you remove it and reinsert it.	A 1756-ENBT module in a secondary chassis sometimes will not synchronize if you remove it and reinsert it. When this happens, its partner 1756-ENBT module shows Primary with No Secondary and you cannot lock the system for an update. To recover, download the project to the secondary controller. Lgx00065410

Update a System That Is Already at Revision 11 or 13

Use this procedure to update the firmware and controllers of your redundant chassis without shutting down your process.

IMPORTANT

- Use this procedure only if your system is already at revision 11 or 13 or you need to update 1756-L55 controllers to the appropriate 1756-L6x controllers.
- Do not use this procedure if:
 - your system is at revision 8.
 - your system is not operating yet.
- During this procedure, you will not be able to use RSLogix 5000 software to change the mode of the controller. Use the keyswitch on the front of the controller to change its mode.
- Leave RSNetWorx for ControlNet software closed or offline throughout this procedure. Otherwise, you will see errors in the RSNetWorx software during the update process.
- During this procedure:
 - Do not make any changes to the RSLogix 5000 project other than the ones called out in this procedure.
 - Make sure no one else makes changes to the project.

Step	Details
------	---------

1. Update the software

A. Go to the tool tray of your computer and shut down RSLinx programming software.



B. Update these software programs.

1. 1757-SRM System Redundancy Module Configuration tool
2. RSLogix 5000 programming software
3. RSLinx programming software
4. RSNetWorx programming software
5. ControlFLASH firmware update kit.

Note: If you are planning to remove version 11 or 13 of your RSLogix 5000 programming software, wait until you have completed and validated your update.

2. Add the latest EDS files.

Start Programs Rockwell Software RSLinx Tools EDS Hardware Installation Tool

3. Put the keyswitches in the REM position.

Put the keyswitch of each redundant controller to the REM position. Otherwise, you will not be able to update the system.


4. Open the 1757-SRM configuration tool for the primary chassis.

A. Start RSLinx programming software.


B. From the Communications pull-down menu, choose RSWho.



C. Browse to and right-click the 1757-SRM module in the primary chassis.




The Module Configuration dialog appears.




Step	Details
------	---------

5. Disqualify the secondary chassis,

- A. Click the Configuration tab.
- B. From the Auto-Synchronization pull-down menu, choose Never.



- C. Click Apply and then Yes.
- D. Select Synchronization.



- E. Select Disqualify Secondary and then Yes.

The secondary chassis is disqualified.




- F. Choose OK.

6. Update the 1757-SRM module in the secondary chassis.

- A. Start the ControlFLASH firmware update tool.
- B. Update the 1757-SRM module in the secondary chassis.


7. Synchronize the chassis.

- A. Go to the 1757-SRM configuration tool.




- B. Select Synchronize Secondary and choose Yes.

The chassis are synchronized.



Step	Details
------	---------


8. Initiate a switchover.



A. Select Initiate Switchover and choose Yes.

B. Wait for the system to switchover.

The other chassis is now the primary chassis.



9. Update the modules in the new secondary chassis or update a 1756-L55M.xx controller to a 1756-L6x controller in a new secondary chassis.

Use the ControlFLASH firmware update tool to update the modules in the new secondary chassis.

Important: Updating controllers is an optional procedure.

Important: To perform this optional procedure, your secondary controller must have at least as much memory as the primary controller.

Primary Controller	Memory Size (Kbytes)	Compatible 1756-L55 Secondary Controller	Compatible 1756-L6x Secondary Controller
L55-M12, L55-M22	750	All	L61, L62, or L63
L55-M13, L55-M23	1536	L55-M13, L55-M23, L55-M14, L55-M24, L55-M16	L61, L62, or L63
L55-M14, L55-M24	3584	L55-M14, L55-M24, L55-M16	L62, L63
L55-M16	7680	L55-M16	L63
L61	2048	None	L61, L62, or L63
L62	4098	None	L62 or L63
L63	8192	None	L63


Important: Please remember that you cannot convert a 1756-L6x controller to a 1756-L55M.xx controller.

Step	Details
10. Prepare the RSLogix 5000 project for the update.	<p data-bbox="646 289 1463 317">A. Start RSLogix 5000 programming software and go online to the primary controller.</p> <p data-bbox="646 352 1255 380">B. Set the watchdog time for each task to this value or greater:</p> <p data-bbox="675 415 1354 443">$\text{Minimum watchdog time} = (2 * \text{maximum_scan_time}) + 150 \text{ ms}$</p> <p data-bbox="675 478 743 506">where:</p> <p data-bbox="675 541 1442 604"><i>Maximum_scan_time</i> is the maximum scan time for the entire task when the secondary controller is synchronized.</p> <p data-bbox="646 640 1003 667">C. Cancel or assemble any test edits.</p> <p data-bbox="646 703 1052 730">D. Remove all SFC forces from the project.</p> <p data-bbox="646 766 1222 793">E. Make sure that you do not need to make any changes to:</p> <ul data-bbox="675 821 1446 926" style="list-style-type: none"><li data-bbox="675 821 1446 884">· I/O Forces — Once you start this procedure, you will not be able to disable or enable I/O forces until you update both chassis.<li data-bbox="675 894 873 921">· I/O configuration. <p data-bbox="675 957 1425 1020">You can make those changes again when the update is done and both chassis synchronize.</p> <p data-bbox="646 1056 841 1083">F. Save the project.</p>

Step	Details
------	---------


11. Change the project revisions.

A. Go offline.



B. Click the Controller Properties icon.


C. Select Change Controller to update the controller's type and revision.



Example: Change the controller from revision 13 to revision 15.


D. Change the revision of each local communication module to match what its revision will be after you update its firmware.

Example: Suppose you plan to update the firmware of each 1756-CNB series D module in the redundant chassis to revision 7.13. In that case, open the properties for each 1756-CNB series D module in the chassis and set the revision to 7.13.



Note: If you cannot select the new revision, then, from the Electronic Keying pull-down menu, choose either Compatible Keying or Disable Keying.


Step	Details
12. Download the project to the secondary controller.	<p>Important: If I/O forces are enabled in the offline project, the software asks if you want to enable the forces in the controller. Even if you choose <i>No</i>, I/O forces stay enabled in the primary controller and become enabled in this controller after you switch over.</p> <p>A. Use RSLogix 5000 programming software to download the project to the controller in the secondary chassis. The secondary chassis has the higher network address of the redundant pair.</p> <p>B. Go offline.</p> <p>Important: Stay offline until you finish this procedure.</p>
13. Lock the system for update.	<p>Important: Do not abort a system lock. Otherwise, you will clear the project from the secondary controller.</p> <p>Important: Do not remove any communication cables while you are locking the system for update.</p> <p>A. Open the 1757-SRM module configuration tool for the primary chassis.</p> <p>B. Click the System Update tab.</p>



C. Select Lock For Update and choose Yes.


D. Wait for the system to lock.

It takes longer than a normal synchronization.



Step**Details**


14. Initiate a Locked Switchover.



A. Select Initiate Locked Switchover and choose Yes.

B. Wait for the system to switchover. A locked switchover takes about as long as a normal switchover.

The other chassis is now the primary chassis.



15. Update the other redundant chassis.

Use the ControlFLASH firmware update tool to update the rest of the modules in the new secondary chassis. You have already updated the 1757-SRM module in this chassis.


Important: If you chose to update your controller as described in Step 9, you also must replace the 1756-L55Mx controller in this chassis with the equivalent 1756-L6x controller.

16. Synchronize the chassis.

A. Go to the 1757-SRM configuration tool for the primary chassis.

B. Click the Configuration tab.

C. From the Auto-Synchronization pull-down menu, choose the desired option.



D. Click Apply and then Yes.

The chassis synchronize.



E. Change the date and time in the 1757-SRM module.

F. Choose OK.

Store a Project to Nonvolatile Memory While Your Process is Running

Use this procedure to store an updated project and firmware to the nonvolatile memory of the controller while your process is running.

IMPORTANT

Use this procedure only with a 1756-L6x controller.

Step	Details
1. Make sure the chassis are synchronized.	Synchronize the chassis if they are not already synchronized.
2. Disqualify the secondary chassis.	<ul style="list-style-type: none"> A. Open the 1757-SRM configuration tool for the primary chassis. B. Set the Auto-Synchronization option to Never. C. Disqualify the secondary chassis.
3. Store the secondary controller's project.	<ul style="list-style-type: none"> A. Go online to the secondary controller. B. Store the project to the nonvolatile memory of the secondary controller. <p>For step-by-step procedures on how to store a project, see the Logix5000 Controllers Common Procedures Programming Manual, publication 1756-PM001.</p> <p>Important: Do not go back online to the secondary controller until you complete the rest of the steps in this procedure.</p>
4. Initiate a switchover.	<ul style="list-style-type: none"> A. Go to the 1757-SRM configuration tool. B. Synchronize the chassis. C. Initiate a switchover.
5. Store the new secondary controller's project.	<ul style="list-style-type: none"> A. Go online to the new secondary controller. B. Store the project to the nonvolatile memory of the secondary controller. <p>For step-by-step procedures on how to store a project, see the Logix5000 Controllers Common Procedures Programming Manual, publication 1756-PM001.</p> <p>Important: Do not go back online to the secondary controller until you complete the rest of the steps in this procedure.</p>
6. Synchronize the chassis.	<ul style="list-style-type: none"> A. Go to the 1757-SRM configuration tool. B. Set Auto-Synchronization to the desired option. C. Synchronize the chassis.

Change CNB modules from Series D to Series E

Use this procedure to replace your 1756-CNB or 1756-CNBR series D modules with newer series E modules.

IMPORTANT

- Use this procedure only if your redundancy system is already at revision 15.
- Replace 1756-CNB modules with 1756-CNB modules and 1756-CNBR modules with 1756-CNBR modules. Otherwise, your chassis will not synchronize.
- Finish this procedure once you start it.
- Each module must be the same series as its partner in the other redundant chassis. If you replace a module with a different series, you must replace the partner module with one of the same series.


Before You Begin

This procedure is easier to complete if you first update the firmware of the 1756-CNB or 1756-CNBR series E modules.

If the CNB modules are	And you	Then
Revision 11.1 or later	→	Go to Actions and start the procedure. You do not need to update the firmware of the modules.
Not revision 11.1 or later	Have a nonredundant chassis with an open slot	<ol style="list-style-type: none"> 1. Add the revision 11 EDS files for the 1756-CNB modules, if you have not already done so. 2. Put one of the 1756-CNB modules into the open slot of the nonredundant chassis. 3. Use ControlFlash software and update the firmware of the 1756-CNB module. 4. Remove the 1756-CNB module. 5. Repeat steps 1...4 for the rest of the 1756-CNB modules. 6. Go to Actions and start the procedure.
	Do not have a nonredundant chassis with an open slot	Go to Actions and start the procedure. You will have to use the secondary chassis to update the modules.

Actions


Step	Details
1. Add the latest EDS files.	Add the revision 11 EDS files for the 1756-CNBR and 1756-CNBR series E modules, if you have not already done so,
2. Prepare the RSLogix 5000 project.	<p>A. Start RSLogix 5000 programming software and go online with the primary controller.</p> <p>B. For each 1756-CNBR or 1756-CNBR series D module in the local chassis, from the Electronic Keying pull-down menu, choose either Compatible Keying or Disable Keying and apply the changes.</p>




3. Open the 1757-SRM module configuration tool for the primary chassis.	<p>C. Save the project.</p> <p>A. Start RSLinx programming software.</p> <p>B. From the Communications pull-down menu, choose RSWho.</p>
---	--






C. Browse to and right-click your 1757-SRM module and choose Module Configuration.



The Module Configuration dialog appears.



Step	Details
4. Disqualify the secondary chassis,	<p>A. Click the Configuration tab.</p> <p>B. From the Auto-Synchronization pull-down menu, choose Never.</p>  <p>C. Click Apply and then Yes.</p> <p>D. Select Synchronization.</p>  <p>E. Select Disqualify Secondary and then click Yes.</p>  <p>F. Click OK.</p>
5. Did you already update the firmware of the series E modules?	<p>Did you already update the firmware of the series E modules?</p> <ul style="list-style-type: none"> · Yes — Go to step 7. · No — Continue with step 6.
6. Update the firmware of the series E modules.	<p>A. Remove the 1757-SRM module from the secondary chassis.</p> <p>B. Set the address of each series E module to the address of its corresponding series D module plus one.</p> <p>C. Replace each series D module with the corresponding series E module.</p> <p>Important: Make sure you connect the correct ControlNet tap to each module.</p> <p>D. Use ControlFlash software to update the firmware of each series E module.</p> <p>E. Remove the series E modules from the secondary chassis and set their addresses to match the original series D modules.</p> <p>F. Repeat steps B...E for the second set of series E modules.</p> <p>G. Put the secondary 1757-SRM module back into the secondary chassis.</p> <p>H. Put one set of series E modules into the secondary chassis.</p> <p>Important: Make sure that you use the correct address, slot, and ControlNet tap for each module.</p> <p>I. Go to step 8.</p>

The secondary chassis is disqualified.

Step	Details
7. Replace the 1756-CNB modules in the secondary chassis.	<p>Replace the 1756-CNB modules in the secondary chassis with series E modules. As you replace the modules:</p> <ul style="list-style-type: none"> · make sure that you set each module to the same address as the module that it is replacing. · make sure that you connect the correct ControlNet tap. To avoid connecting the wrong tap, replace the modules one at a time and reconnect the ControlNet tap.
8. Update the keeper signatures of the 1756-CNB modules.	<p>A. Start RSNetWorx for ControlNet software, and open the network configuration file. B. Go online with the network. You do not have to browse the entire network. C. Select Network and choose Keeper Status.</p>



- D. Select the node number of the secondary 1756-CNB module and click Update Keeper.

Keeper Capable Node	Active Keeper	Valid Keeper	Keeper Signature
Offline File	N/A	N/A	0xd2978909
01	YES	YES	0xd2978909
02	NO	YES	0xd2978909
03	NO	NO	Unconfigured
05	NO	YES	0xd2978909
06	NO	YES	0xd2978909

- E. Verify that the keeper signature has been updated.

Keeper Capable Node	Active Keeper	Valid Keeper	Keeper Signature
Offline File	N/A	N/A	0xd2978909
01	YES	YES	0xd2978909
02	NO	YES	0xd2978909
03	NO	YES	0xd2978909
05	NO	YES	0xd2978909
06	NO	YES	0xd2978909

- F. Repeat steps D and E for the other 1756-CNB modules in the secondary chassis.
G. Click Close.


Step	Details
9. Reset the secondary 1756-CNB modules.	<p>A. Cycle power to the secondary chassis.</p> <p>B. Select the Synchronization Status tab, and verify that the modules are fully compatible.</p>

1757-SRM REDUNDANCY MODULE

Module Info | Configuration | Synchronization | **Synchronization Status** | Event Log | System Update


Slot	% Complete	Module	Secondary Readiness	State	Compatibility
0	---	<empty>	---	---	---
1	---	<empty>	---	---	---
2	0	1756-L63	Disqualified	Primary	Full
3	---	<empty>	---	---	---
4	0	1756-CNBR	Disqualified	Primary	Full
5	0	1757-SRM	Disqualified	Primary	Full
6	---	<empty>	---	---	---
7	---	<empty>	---	---	---
8	0	1756-CNBR	Disqualified	Primary	Full
9	0	1756-ENBT	Disqualified	Primary	Full
10	---	<empty>	---	---	---

10. Synchronize the secondary chassis.
- A. Select Synchronization.




- B. Select Synchronize Secondary and choose Yes.
- C. Wait for the chassis to synchronize.

The chassis are synchronized.




11. Initiate a switchover.



Select Initiate Switchover and choose Yes.

12. Replace the 1756-CNB modules in the new secondary chassis. Repeat steps 7...9 for the 1756-CNB modules in the new secondary chassis.

Step	Details
13. Synchronize the chassis.	<p data-bbox="646 289 1354 317">A. Go to the 1757-SRM module configuration tool for the primary chassis.</p> <p data-bbox="646 346 951 373">B. Select the Configuration tab.</p> <p data-bbox="646 403 1398 430">C. From the Auto-Synchronization pull-down menu, choose the desired option.</p> <div data-bbox="771 464 1477 688"></div> <p data-bbox="646 716 867 743">D. Click Apply and Yes.</p>

Rockwell Automation Support

Rockwell Automation provides technical information on the Web to assist you in using its products. At <http://support.rockwellautomation.com>, you can find technical manuals, a knowledge base of FAQs, technical and application notes, sample code and links to software service packs, and a MySupport feature that you can customize to make the best use of these tools.

For an additional level of technical phone support for installation, configuration, and troubleshooting, we offer TechConnect support programs. For more information, contact your local distributor or Rockwell Automation representative, or visit <http://support.rockwellautomation.com>.

Installation Assistance

If you experience a problem within the first 24 hours of installation, please review the information that's contained in this manual. You can also contact a special Customer Support number for initial help in getting your product up and running.

United States	1.440.646.3434 Monday – Friday, 8 a.m. – 5 p.m. EST
Outside United States	Please contact your local Rockwell Automation representative for any technical support issues.

New Product Satisfaction Return

Rockwell Automation tests all of its products to ensure that they are fully operational when shipped from the manufacturing facility. However, if your product is not functioning and needs to be returned, follow these procedures.

United States	Contact your distributor. You must provide a Customer Support case number (call the phone number above to obtain one) to your distributor in order to complete the return process.
Outside United States	Please contact your local Rockwell Automation representative for the return procedure.

Allen-Bradley, ControlLogix, RSLinx, RSLinx Enterprise, RSLogix 5000, RSNetWorx, Rockwell Automation, and Tech Connect are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1756-RN668A-EN-E - March 2009

Supersedes Publication 1756-RN628E-EN-E - March 2007

PN-43645

Copyright © 2009 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.