



Using 1771-IBN and 1771-IVN Modules in a PLC-5 Extended Local System

Release Notes

General

This release note defines a problem that exists, under certain conditions, with 1771-IBN 10–30V dc input module and 1771-IVN 10–30V dc input modules. This release note provides:

- a description of the problem
- when it can occur
- how to identify affected modules
- what to do if you have an affected module

Description of Problem

When using certain 1771-IBN or 1771-IVN modules in a PLC-5/40L or -5/60L (1785-L40L or -L60L) extended local system, **and** your system uses a 1771-ALX in the extended local chassis, it is possible to power up in a mode that could result in **unpredictable operation caused by misaddressed inputs and outputs in the chassis**.

When It Can Occur

These conditions occur intermittently at power up under certain configurations. A system powered up and properly running won't exhibit this problem. Temporary power outages or brownouts can momentarily interrupt system power, and cause this problem to occur.

How to Identify Affected Modules

Affected modules are identified by part numbers on the backplane edge of the printed circuit board (see table), or component layout (see illustration).

Catalog Number	Circuit Board Part Number ¹	Build Date	What to do?
1771-IBN	961336□□	June 1993 to February 1995	Affected Modules – Replace
1771-IVN	961340□□		
1771-IBN	See note 2 below	Prior to June 1993	Unaffected Modules – Do Not Replace
1771-IVN	See note 2 below		
1771-IBN B	961336□□	June 1993 to February 1995	
1771-IVN B	961340□□		

¹ Last 2 digits can be any number


² These modules do not have a 961□□□□□ number on the backplane edge of the circuit board. Refer to the illustration.

Release Notes

Using 1771-IBN and 1771-IVN Modules in a PLC-5
Extended Local System

Note: Modules identified as Series B with the above circuit board part numbers are **unaffected** modules. Modules built prior to June 1993 are also **unaffected** modules.

You can identify pre-June 1993 modules by viewing the module from the bottom.



What to Do If You Have an Affected Module

If it is necessary to cycle power to your system or individual chassis while affected modules are in use:

1. Shut off power to the chassis.
2. Remove extended local cable from the chassis.
3. Power up the chassis.



ATTENTION: To reduce the possibility of unintended system operation, make certain that your processor is **not** in RUN mode before you reattach the extended local cable.

4. Reattach the extended local cable.

We strongly recommend immediate replacement or repair of any affected modules. For details, contact your local A-B district office.



Allen-Bradley, a Rockwell Automation Business, has been helping its customers improve productivity and quality for more than 90 years. We design, manufacture and support a broad range of automation products worldwide. They include logic processors, power and motion control devices, operator interfaces, sensors and a variety of software. Rockwell is one of the world's leading technology companies.



Worldwide representation.

Argentina • Australia • Austria • Bahrain • Belgium • Brazil • Bulgaria • Canada • Chile • China, PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Ecuador • Egypt • El Salvador • Finland • France • Germany • Greece • Guatemala • Honduras • Hong Kong • Hungary • Iceland • India • Indonesia • Ireland • Israel • Italy • Jamaica • Japan • Jordan • Korea • Kuwait • Lebanon • Malaysia • Mexico • Netherlands • New Zealand • Norway • Pakistan • Peru • Philippines • Poland • Portugal • Puerto Rico • Qatar • Romania • Russia-CIS • Saudi Arabia • Singapore • Slovakia • Slovenia • South Africa, Republic • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • United Arab Emirates • United Kingdom • United States • Uruguay • Venezuela • Yugoslavia

Allen-Bradley Headquarters, 1201 South Second Street, Milwaukee, WI 53204 USA, Tel: (1) 414 382-2000 Fax: (1) 414 382-4444