



Stratix 6000 Ethernet Managed Switches

Catalog Numbers 1783-EMS04T, 1783-EMS08T

Topic	Page
About This Publication	1
Corrected Anomalies	1
Additional Resources	2

About This Publication

These release notes correspond to series B of the Stratix 6000™ Ethernet managed switch, firmware revisions 0.12 and 0.54. The series B switch is a direct replacement for the series A switch.

IMPORTANT

The following requirements apply to this release:

- Firmware revisions 0.11, 0.53, or later are required for the Stratix 6000 series B switch. Earlier firmware revisions **will not run** on a series B switch.
- Firmware revisions 0.12 and 0.54 are backwards compatible and **will run** on an existing Stratix 6000 series A switch.
- This release requires Add-on-Profile (AOP), version 3.01.2939 or later.

IMPORTANT

To preserve the integrity of exact match keying, series A and series B switches identify the same CIP firmware revision differently:

- Series A switches, revision 0.12 or 0.54, identify CIP firmware as revision 2.002.
- Series B switches, revision 0.12 or 0.54, identify CIP firmware as revision 3.002.

Corrected Anomalies

This section describes corrected anomalies with these revisions.

Table 1 - Corrected Anomalies with Revisions 0.12 and 0.54

Corrected Anomaly	Description
IGMP snooping stops	CORRECTED: IGMP snooping can stop functioning after a few minutes under certain configurations.
IGMP convergence time slows	CORRECTED: IGMP network convergence time can be slow when adding or removing a redundant path.
Incorrect port duplex appears on Home page	CORRECTED: The wrong port duplex state appears on the Home page of the web interface for a selected port until manually disabling or enabling the port after an auto-negotiated configuration change.



Additional Resources

These documents contain additional information concerning related products from Rockwell Automation.

Resource	Description
Stratix Ethernet Switch Specifications, publication 1783-TD001	Provides technical specifications for Stratix Ethernet switches.
Stratix 6000 Ethernet Managed Switches Installation Instructions, publication 1783-IN004	Describes how to get started installing and configuring Stratix 6000 switches.
Stratix 6000 Ethernet Managed Switches User Manual, publication 1783-UM001	Provides information about using Stratix 6000 switches.
Industrial Automation Wiring and Grounding Guidelines, publication 1770-4.1	Provides general guidelines for installing a Rockwell Automation industrial system.
Product Certifications website, http://www.ab.com	Provides declarations of conformity, certificates, and other certification details.

You can view or download publications at <http://www.rockwellautomation.com/literature>. To order paper copies of technical documentation, contact your local Allen-Bradley distributor or Rockwell Automation sales representative.

Allen-Bradley, Rockwell Software, Rockwell Automation, and Stratix 6000 are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

Rockwell Otomasyon Ticaret A.Ş., Kar Plaza İş Merkezi E Blok Kat:6 34752 İçerenköy, İstanbul, Tel: +90 (216) 5698400

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation NV, Pegasus Park, De Kleetlaan 12a, 1831 Diegem, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1783-RN003D-EN-P - January 2013

Supersedes Publication 1783-RN003C-EN-P - August 2011

Copyright © 2013 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.