![PlantPAx Process Automation System logo]

# PlantPAx Process Automation System

Catalog Numbers 7477-ISVS100, 7477-ISVS250, 7477-IC2VC

1 **Attach hardware if mounting is required.**

2 **Connect peripherals.**

PS/2   PS/2

3 **Connect power and turn on the computer.**

The computer will boot to a Windows Setup Wizard.

4 **Click Next to enter the Windows Setup Wizard.**

5 **Read and accept the End User License Agreement (EULA).**

6 **Gather this information and complete the Windows Setup Wizard.**

Regional and Language Settings	
Name	
Organization	
Server Licensing Mode (For Windows Server bundles only)	5 CALS
Computer Name	
Windows Administrator Password	
Network configuration: Workgroup or Domain	
Workgroup/Domain Name	

When the Windows Setup Wizard is complete, the computer will restart automatically.

The new Windows desktop may take a few minutes to load.

7 **Log in to Windows using the administrator password set in step 6.**

The computer is now setup. To begin configuration of your Process System, see the PlantPAx Server and Workstation user manual, located in the PlantPAx documentation folder on your desktop.

Additional Resources

For additional information refer to these publications.

Publication Number	Description
PlantPAx Server and Workstation user manual, publication 7477-UM001.	Provides information for configuring software on the Process Automation System Server and Operator Workstation.

You can view or download publications at http://literature.rockwellautomation.com.

Installation Assistance

If you experience a problem within the first 24 hours of installation, please review the information in this document. You can also contact a special Customer Support number for initial help in getting your product up and running.

United States	1.440.646.3434 Monday – Friday, 8am – 5pm EST
Outside United States	Please contact your local Rockwell Automation representative for any technical support issues.