CERTIFICATE OF COMPLIANCE

Certificate Number	E228422
Report Reference	E228422-20230503
Issue Date	2023-SEPTEMBER-14
Issued to:	ROCKWELL AUTOMATION INC. 1201 S 2nd St Milwaukee, WI 53204-2410 United States
This certificate confirms that representative samples of	POWER CIRCUIT AND MOTOR-MOUNTED APPARATUS - COMPONENT See Addendum Page for Model(s)
	Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.
Standard(s) for Safety:	UL 508 and CSA C22.2 No. 14-10
Additional Information:	See UL Product iQ® at https://iq.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number	E228422
Report Reference	E228422-20230503
Issue Date	2023-SEPTEMBER-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Incremental encoders, Models - 844DS-BMOCTFW, 844DS-BMOCTCS, 844DS-BMO1HCK, 844DS-BMO1HCS, 844DS-BMO1HFW, 844DS-BMOCHLS, 844DS-BMOCHCV, 844DS-BMOCHCK, 844DS-BMOCHDB, 844DS-BMOCHFS, 844DS-BMOCHDR, 844DS-BMOCHDS, 844DS-BMOCHCR, 844DS-BMOCHCS, 844DS-BMOCHFW, 844DS-BMO1TCS, 844DS-BMO1TFW, 844DS-BMOCTLS, 844DS-BMOCTCK, 844DS-BMOCTDB, 844DS-BMOCTFS, 844DS-BMOCTDR, 844DS-BMOCTDS, 844DS-BMOCTCR, 844DS-BMO1HCR, 844DS-BNODHDR, 844DS-BNODHDB, 844DS-BNODHCV, 844DS-BNODHCS, 844DS-BNODHCR, 844DS-BNODHCK, 844DS-BNOCTLS, 844DS-BNOCTFW, 844DS-BNOCTFS, 844DS-BNOCTDS, 844DS-BNOCTDR, 844DS-BNOCTDB, 844DS-BNOCTCV, 844DS-BNOCTCS, 844DS-BNOCTCR,844DS-BNOCTCK, 844DS-BNOCHLS, 844DS-BNOCHFW, 844DS-BNOCHFS, 844DS-BNOCHDS, 844DS-BNOCHDR, 844DS-BNOCHDB, 844DS-BNOCHCV, 844DS-BNOCHCS, 844DS-BNOCHCR, 844DS-BNOCHCK, 844DS-BNO1TLS, 844DS-BNO1TFW, 844DS-BNO1TFS, 844DS-BNO1TDS, 844DS-BNO1TDR, 844DS-BNO1TDB, 844DS-BNO1TCV, 844DS-BNODHDS, 844DS-BNOJTLS, 844DS-BNOJTFW, 844DS-BNOJTFS, 844DS-BNOJTDS, 844DS-BNOJTDR, 844DS-BNOJTDB, 844DS-BNOJTCV, 844DS-BNOJTCS, 844DS-BNOJTCR, 844DS-BNOJTCK, 844DS-BNOJHLS, 844DS-BNOJHFW, 844DS-BNOJHFS, 844DS-BNOJHDS, 844DS-BNOJHDR844DS-BNOJHDB, 844DS-BNOJHCV, 844DS-BNOJHCS, 844DS-BNOJHCR, 844DS-BNOJHCK, 844DS-BNODTLS, 844DS-BNODTFW, 844DS-BNODTFS, 844DS-BNODTDS, 844DS-BNODTDR, 844DS-BNODTDB, 844DS-BNODTCV, 844DS-BNODTCS, 844DS-BNO1TFW, 844DS-BNO1TFS, 844DS-BNO1TDS, 844DS-BNO1TDR, 844DS-BNO1TDB, 844DS-BNO1TCV, 844DS-BNODHDS, 844DS-BNOJTLS, 844DS-BNOJTFW, 844DS-BNOJTFS, 844DS-BNOJTDS, 844DS-BNOJTDR, 844DS-BNOJTDB, 844DS-BNOJTCV, 844DS-BNOJTCS, 844DS-BNOJTCR, 844DS-BNOJTCK, 844DS-BNOJHLS, 844DS-BNOJHFW, 844DS-BNOJHFS, 844DS-BNOJHDS, 844DS-BNOJHDR, 844DS-BNOJHDB, 844DS-BNOJHCV, 844DS-BNOJHCS, 844DS-BNOJHCR, 844DS-BNOJHCK, 844DS-BNODTLS, 844DS-BNODTFW, 844DS-BNODTFS, 844DS-BNODTDS, 844DS-BNODTDR, 844DS-BNODTDB, 844DS-BNODTCV, 844DS-BNODTCS, 844DS-BNODTCR, 844DS-BNODTCK, 844DS-BNODHLS, 844DS-BNODHFW, 844DS-BNODHFS, 844DS-BNO1TCS, 844DS-BMODTFS, 844DS-BMODTDS, 844DS-BMODTDR, 844DS-BMODTDB, 844DS-BMODTCV, 844DS-BMODTCS, 844DS-BMODTCR, 844DS-BMODTCK, 844DS-BMODHLS, 844DS-BMODHFW, 844DS-BMODHFS, 844DS-BMODHDS, 844DS-BMODHDR, 844DS-BMODHDB, 844DS-BMODHCV, 844DS-BMODHCS, 844DS-BMODHCR, 844DS-BMODHCK, 844DS-BMOCTCV, 844DS-BMO1TLS, 844DS-BMO1TFS, 844DS-BMO1TDS, 844DS-BMO1TDR, 844DS-BMO1TDB, 844DS-BMO1TCV, 844DS-BMO1TCR, 844DS-BMO1TCK, 844DS-BMO1HLS, 844DS-BMO1HFS, 844DS-BMO1HDS, 844DS-BMO1HDR, 844DS-BMO1HDB, 844DS-BMO1HCV, 844DS-BMODTFW, 844DS-BNO1TCR, 844DS-BNO1TCK, 844DS-BNO1HLS, 844DS-BNO1HFW, 844DS-BNO1HFS, 844DS-BNO1HDS, 844DS-BNO1HDR, 844DS-BNO1HDB, 844DS-BNO1HCV, 844DS-BNO1HCS, 844DS-BNO1HCR, 844DS-BNO1HCK, 844DS-BMOJTLS, 844DS-BMOJTFW, 844DS-BMOJTFS, 844DS-BMOJTDS, 844DS-BMOJTDR, 844DS-BMOJTDB, 844DS-BMOJTCV, 844DS-BMOJTCS, 844DS-BMOJTCR, 844DS-BMOJTCK, 844DS-BMOJHLS, 844DS-BMOJHFW, 844DS-BMOJHFS, 844DS-BMOJHDS, 844DS-BMOJHDR, 844DS-BMOJHDB, 844DS-BMOJHCV, 844DS-BMOJHCS, 844DS-BMOJHCR, 844DS-BMOJHCK, 844DS-BMODTLS.

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at http://ul.com/aboutul/locations/