CERTIFICATE OF COMPLIANCE

Certificate Number	E143423
Report Reference	E143423-20200707
Issue Date	2020-JULY-30
Issued to:	ROCKWELL AUTOMATION 2 Executive Dr. Chelmsford, MA 01824 USA
This certificate confirms that representative samples of	Proximity Switches See Addendum page for models
	Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.
Standard(s) for Safety:	Standard for Industrial Control Equipment, UL508 & CSA C22.2 No. 14-18
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number	E143423
Report Reference	E143423-20200707
Issue Date	2020-JULY-30

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Proximity switch, capacitive type, Models 875L-M8NP18-A2, 875L-M8NN18-A2, 875L-M8CP18-A2, 875L-M8CN18-A2, 875L-N12NP18-A2, 875L-N12NN18-A2, 875L-N12CP18-A2, 875L-N12CN18-A2, 875L-M8NP18-D4, 875L-M8NN18-D4, 875L-M8CP18-D4, 875L-M8CN18-D4, 875L-N12NP18-D4, 875L-N12NN18-D4, 875L-N12CP18-D4, 875L-N12CN18-D4, 875L-M16NP30-A2, 875L-M16NN30-A2, 875L-M16CP30-A2, 875L-M16CN30-A2, 875L-N25NP30-A2, 875L-N25NN30-A2, 875L-N25CP30-A2, 875L-N25CN30-A2, 875L-M16NP30-D4, 875L-M16NN30-D4, 875L-M16CP30-D4, 875L-M16CN30-D4, 875L-N25NP30-D4, 875L-N25NN30-D4, 875L-N25CP30-D4, 875L-N25CN30-D4, 875F-M10NP34-A2, 875F-M10NN34-A2, 875F-M10CP34-A2, 875F-M10CN34-A2,. 875F-M10NP34-FP02, 875F-M10NN34-FP02, 875F-M10CP34-FP02, 875F-M10CN34-FP02,

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/