



ControlLogix Analog Servo Modules Revision 15

Catalog Number 1756-HYD02, 1756-M02AE, 1756-M02AS

When to Use These Release Notes

Use these release notes for this revision:

Module	Catalog number	Revision
ControlLogix 2-axis hydraulic servo module	1756-HYD02	15.1
ControlLogix 2-axis analog encoder servo module	1756-M02AE	15.1
ControlLogix 2-axis analog SSI servo module	1756-M02AS	15.1



Compatible Revisions

To use this revision, update your system as follows:

Update this	To this revision
RSLinx® software	2.50 or later
RSLogix™ 5000 software	15
ControlLogix® controller	15

Before You Update Your Module

ATTENTION Before you update your module, inhibit the module.



This disables the axes and makes it easier to update the module.

Enhancements

For a list of enhancements, see *ControlLogix Controllers Revision 15 Release Notes*, publication 1756-RN620.

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1756-RN625A-EN-E - September 2005

Supersedes Publication -

PN 957988-39

Copyright © 2005 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.