



OEM Products

Isolation Switch with Fuse Clips Instruction Sheet

Handling

Carefully unpack the item and inspect it for damage that may have occurred during shipping. Immediately report any damage to the claims office of the carrier. Rockwell Automation will render reasonable assistance in resolving a damage claim.

Identification

Verify the catalog and part numbers of the isolation switch.

Options and Catalog Numbers

Switch Size	Non-Load-Break Isolation Switch Options	Catalog Number
400 A	Clip-on fuse clips ❶	1503S-4C
	Bolt-on fuse clips ❷	1503S-4B
600 A	Clip-on fuse clips ❶	1503C-6C
	Bolt-on fuse clips ❷	1503C-6B
800 A	Bolt-on fuse clips ❷	1503C-8B

❶ Provision for a 76.20-mm (3-inch) wide by 403.35-mm (15.88-inch) long barrel.

❷ Provision for a 76.20-mm (3-inch) wide by 454.25-mm (17.88-inch) long barrel.

Storage

If the isolation switch will not be installed immediately after receipt, store it in a clean, dry and dust-free environment. Humidity should not exceed 95%, non-condensing.

Installation and Technical Information

Refer to *Control Components - Installation Instructions, Publication 1503-5.0* for complete installation instructions and technical information for the Isolation Switch with fuse clips.

Additional Publications

Order additional copies of instruction manuals for all Allen-Bradley medium voltage products from the Automation Bookstore at www.theautomationbookstore.com.

Rockwell Automation

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0660

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 109 Cyberport Road, Hong Kong, Tel: (852) 2867 4788, Fax: (852) 2508 1846

Medium Voltage Business, 135 Dundas Street, Cambridge, ON N1R 5X1 Canada, Tel: (1) 519 623-1810, Fax: (1) 519 623-8930 Web Site: www.ab.com/mvb